

SAFETY RECALL NOTICE



Bombardier Recreational Products Inc.

565 de la Montagne Street
Valcourt, Québec, Canada J0E 2L0
T 450.532.2211 F 450.532.5133

www.brp.com

Date: December 7, 2007

Re: Contaminated Carburetors

Dear Ski-Doo Owner,

This notice is sent to you in accordance with the requirements of the Consumer Product Safety Act, the Canada Motor Vehicle Safety Act and other applicable laws.

What is the reason for this notice?

In cooperation with Transport Canada and the U.S. Consumer Product Safety Commission, Bombardier Recreational Products Inc. and BRP US Inc. ("BRP") are conducting a voluntary safety recall of certain 2008 Ski-Doo models. **Our records indicate that you are the owner of a potentially affected vehicle.**

What is the potential problem?

Carburetors could be contaminated by fine steel beads, this can affect the free return to idle position. This could lead to loss of speed control and possible collision with bystanders, a fixed object or another vehicle and potentially cause serious injuries or even death.

What should you do?

Immediately stop using your vehicle, call an authorized BRP dealer and make an appointment to have your vehicle repaired. *The dealer will perform this work at no charge to you.*

What to do if you feel this notice is an error?

This notice was mailed to you according to the most current information we have available. If you no longer own this vehicle or some information in this notice is incorrect, please contact BRP at your earliest convenience.

If you have questions, need assistance, or to find your nearest authorized BRP dealer:

- Visit www.skidoo.com
- In the US and Canada: 1-888-638-5397, 8:00 to 18:00 Eastern time

We apologize for any inconvenience this may cause you. Thank you for your immediate attention to this matter.

Sincerely,

After-Sales Service Department
Bombardier Recreational Products Inc.

Ski-Doo
Lynx
Sea-Doo
Evinrude
Johnson
Rotax
Can-Am